


Discussion

Determining the locus of failure in multilayer laminates is often the first step in understanding the cause of failure. In many cases a fraction of a monolayer of contamination is enough to weaken a bond to the point of failure. In this example we examine mating faces from a failed Cu-laminate (see schematic below). X-ray photoelectron spectroscopy (XPS/ESCA) is used because of its surface sensitivity and ability to quantitatively identify not only the elements present but also determine their chemical or oxidation state.

As expected, copper was detected on both sides of the failed interface. Significant quantities of Ni⁰, Ni²⁺, Mo⁰, Mo⁴⁺, Mo⁶⁺ and PO₄³⁻ were detected on both sides of the failed interface by XPS. Carbon was also detected, but likely came from adsorption of organic species during the brief air exposure.


To probe the thickness of the Ni, Mo and P containing layers, the surfaces were depth profiled using a focused beam of argon ions. The resulting profiles reveal a roughly 10 Å phosphate layer on both sides of the failed interface. The P concentration is relatively low (2.5%); however, it is determined to be present as PO₄³⁻, meaning the total amount of phosphate at the interface is >5X the P concentration. The cation associated with the phosphate is likely either Cu⁺, Mo^{x+} or possibly H⁺ (hydrogen is not detected by XPS). Beneath the phosphate layer on the Carrier side there is ~100Å Ni₂Mo layer. A small amount of Ni was detected on the mating foil surface.




XPS was used to determine that adhesive failure occurred at a Ni₂Mo-Cu interface as a result of a high concentration of phosphate (see schematic in lower right).

Table 1. Concentration of Elements Detected on Failed Surfaces (in atom%)

Sample	C	O	P	S	Cl	Ni	Cu	Mo
Cu thin foil side	28.8	34.5	2.5	0.5	0.9	8.9	20.2	3.7
Cu carrier side	29.4	42.7	2.6	0.8	0.1	10.5	3.1	10.9



Schematic of laminate structure and failure path based on XPS data



Visit www.eaglabs.com for more information about all of EAG's services and solutions.

EAG Limited Administrative Offices, 810 Kifer Road, Sunnyvale, CA 94086 phone: 408 530 3500

Copyright © 2008 EAG Limited. All rights reserved. EAG, the EAG logo, are registered trademarks of EAG Limited.

Evans Analytical Group, Charles Evans & Associates, Thin Film Analysis, Inc., Applied Microanalysis Labs, Inc., AMIA Labs, Advanced Materials Engineering Research, Cascade Scientific Ltd., Cascade Scientific GmbH, Nano Science Corporation, Shiva Technologies, Inc., Shiva Technologies Europe SAS, Accurel Systems International Corporation, Micro Electronic Failure Analysis Services, Inc., DSL Labs Inc., White Mountain Labs LLC, are service marks of EAG Limited. All other company, product and service names may be trademarks of their respective companies. While every effort is made to ensure the information given is accurate, EAG Limited does not accept liability for any errors or mistakes which may arise. All information is subject to change without notice.